

Cut apart a 2804-1 only to find for the second time the paper pleats had crushed the perforated tube:



There should be an annular space between the inner standpipe and the outer perforated tube:





The perforated tube could not stand up to the force created by the oil flowing inward through the paper pleats:





04 OCT 10 (sun)  
FROM PH2804-1