



2005 FERRARI 612 SCAGLIETTI - RED

VIN: ZFFAA54A550140541 Work Order #: 1181201

FLORIDA AUTO AUCTION - ORLANDO

VIN: ZFFAA54A550140541
Body Style: 2 Door Coupe
Ext Color/Code: RED
Int Color/Code: BLK
Mileage: 15,471
Seller: CHASE
 AUTOMOTIVE
 FINANCE
Title State: FL
Certified: No
Condition/Grade: Grade 3, Average
Sale: 29
Lane: 21
Run: 1
Inspection: JPerez 03/23/2007
Drivable: Yes



VEHICLE INFORMATION

MECHANICAL

12 Cylinder Gas
 Automatic
 Pwr Brakes
 5.7 L

INTERIOR

Worn
 BLK - Leather
 Odometer - 6 Digits Digital -
 Operable
 Int Odor: OK
 Regular Dash

OPTIONS

Pwr Lock	Pwr Steering
Pwr Window	Pwr Seats - Both
A/C	Rear Defrost
CD Player	Dual Air Bags
Power Tilt Steering	Power Telescopic
ABS Brakes	Steering
Television	Memory Seat
Traction Control	US EPA Label
Power Mirrors	Trip Counter
Power	Floor Mats
Trunk/Liftgate	Tinted Windows

FLUID LEVELS

Fuel Level: Empty

TIRES AND WHEELS

LF - 9/32 MICHELIN 275/35ZR19 Master Key - 3
 RF - 8/32 MICHELIN
 275/35ZR19
 LR - 5/32 MICHELIN
 335/30ZR20
 RR - 6/32 MICHELIN
 335/30ZR20
 SP -
 Tire Condition: Good
 Wheels - Alloy

KEYS

ANNOUNCED CONDITION: INDASH TV/RIVET HOLES IN TRUNK

INTERNET REMARKS:


REMARKS/ADDITIONAL DAMAGE:

DISCLOSURES:

NOTES TO CONSIGNOR: **AFTERMARKET RADIO/MISSING FACTORY WIRE

REMARKS: **AFTERMARKET RADIO/MISSING FACTORY WIRE

2005 FERRARI 612 SCAGLIETTI - REDVIN: ZFFAA54A550140541 **Work Order #:** 1181201**FLORIDA AUTO AUCTION - ORLANDO****DAMAGES**

	DESCRIPTION	CONDITION	SEV.	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Deck Lid	Inop	Vsbl Close Insp	1.00	.00	.00	1.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Overall Picture	Ovrall Picture		.00	.00	.00	.00
	Front Bumper	Prev Repair		.00	.00	.00	.00
	Hood	Prev Repair		.00	.00	.00	.00
	LF Fender	Dings	PDR/2	.00	.00	.00	.00
	LF Fender	Prev Repair		.00	.00	.00	.00
	LF Door	Dings	PDR/2	.00	.00	.00	.00
	L Qtr Panel	Dings	PDR/2	.00	.00	.00	.00
	Rear Bumper	Scratch Light	1" to 2"	.00	.00	.00	.00
	RF Fender	Prev Repair	Acceptable	.00	.00	.00	.00
	RF Door	Prev Repair	Acceptable	.00	.00	.00	.00
	RR Wheel	Mult Scratches	1" to 2"	.00	.00	.00	.00
	CD Player	After Market	Vsbl Close Insp	.00	.00	.00	.00
	Speakers	After Market	Vsbl Close Insp	.00	.00	.00	.00
	TOTALS			1.00	.00	.00	1.00

REPAIRED

	DESCRIPTION	CONDITION	SEV.	REPAIR HOURS	PAINT HOURS	PART HOURS	TOTAL HOURS
	Overall Vehicle	Multiple Chips		.00	.00	.00	.00
	Front Bumper	Dent/Paint Dmg	Vsbl Close Insp	2.00	3.20	.00	5.20
	TOTALS			2.00	3.20	.00	5.20

Print